



East 6427 Rutter Rd., Felts Field, Spokane, WA 99212

[509]535-4401 Fax[509]543-2025

S.I.L. NO. 00-560-03

Service Information Letter

FROM: JetProp LLC

11 July 2000

SUBJECT: Engine Mount Cracks at Nose Gear Actuator

Models Affected: JetProp DLX (STC SA00541SE) Numbers 1 through 31

Background. Two instances have been reported where a crack in the engine mount pad attachment for the nose gear actuator was found during an inspection.

Action Required. Conduct a visual inspection of the engine mount area around the nose gear actuator attachment. This inspection can be accomplished from underneath the aircraft without removing the cowling. The inspection should be accomplished prior to the next flight. Please notify Rocket Engineering at (509) 535-4401 as soon as the inspection has been completed with the results regardless of whether any cracks are found. If a crack is found, coordinate repairs with Rocket Engineering. If no cracks are found, re-inspect the mount every 25 hours.

Rocket Engineering is dedicated to continuing to improve the JetProp DLX Conversion and to supporting our customers. Thank you for your assistance.

Regards,

Darwin Conrad
President